



## Inspection report

Date: <b>18/03/2009</b>	Job N°: <b>T 6246</b>	Weather: <b>No rain or snow</b>	Operator: <b>Dan</b>	section number: <b>3</b>	PLR: <b>00088900 X</b>
Video Volume No.: <b>DVD 001</b>	Flow Ctrl: <b>No flow control</b>	Temperature: <b>above freezing</b>	Year laid:	Cleaned: <b>Yes</b>	Strat. Drain:

Road: <b>Wick Road</b>	Div/Dist:	start MH: <b>00088900</b>
Place: <b>London</b>	Drain. Area:	end MH: <b>Node</b>
Location:	Standard: <b>BS EN 13508-2:2003</b>	Total length: <b>2.4 m</b>

Purpose: <b>Suspected operational problem</b>	Shape/Size: <b>Circular 150mm</b>
Type: <b>Gravity drain/sewer</b>	Material: <b>Vitrified clay (i.e. all clayware)</b> Pipe length: -
Use: <b>Surface water</b>	Lining: Lining Type:

Comment: **Time 00 01 14**

