




# Inspection report

Date: <b>05/06/2009</b>	Job N°: <b>T 6323</b>	Weather: <b>No rain or snow</b>	Operator: <b>Dan</b>	section number: <b>1</b>	PLR: <b>FW01 X</b>
Video Volume No.: <b>Vid 001</b>	Flow Ctrl: <b>No flow control</b>	Temperature: <b>above freezing</b>	Year laid:	Cleaned: <b>No</b>	Strat. Drain:


Road: <b>The Hill Avenue</b>	Div/Dist:	start MH: <b>FW01</b>
Place: <b>Number 12</b>	Drain. Area:	end MH: <b>Offsite</b>
Location:	Standard: <b>BS EN 13508-2:2003</b>	Total length: <b>28.8 m</b>

Purpose: <b>Post inspection of repairs or renovations</b>	Shape/Size: <b>Circular 100mm</b>
Type: <b>Gravity drain/sewer</b>	Material: <b>Vitrified clay (i.e. all clayware)</b> Pipe length: <b>0.7m</b>
Use: <b>Foul</b>	Lining: Lining Type:

Comment: **Time 00 00 00**


1:124	position	code	observation	grade
Depth: 0.29 / Cover level: 99.58 / Invert level: 99.29 /				
	0.00	IC	Start node type, inspection chamber, reference number: FW01	
	0.00	WL	Water level 0 % height/diameter	0
	1.10	CCJ	Crack Circumferential at joint from 04 to 11 o'clock	2
	1.60	CC	Crack Circumferential from 07 to 04 o'clock	2
	2.40	OJM	Open joint medium	1
	2.40	GP	General Condition photograph	0
	3.80	DES	Settled deposits fine 5 % cross-sectional area loss	1
	4.30	LR	Line of drain/sewer deviates right	
	4.50	LL	Line of drain/sewer deviates left	
	6.20	JN	Junction at 09 o'clock dia 100 mm	0
	7.00	CN	Connection at 11 o'clock, dia 100 mm	0
	9.30	S1 DES	Settled deposits fine 10 % cross-sectional area loss, Start	1
	9.40	BJ	Broken Pipe at joint from 09 to 01 o'clock	4
	9.40	GP	General Condition photograph	0
	10.90	F1 DES	Settled deposits fine 15 % cross-sectional area loss, Finish	1
	11.80	CL	Crack Longitudinal at 10 o'clock	2
	11.80	CL	Crack Longitudinal at 12 o'clock	2
	11.90	JN	Junction at 09 o'clock dia 100 mm	0
	15.70	JN	Junction at 09 o'clock dia 100 mm	0
	15.90	H	Hole in sewer from 10 to 12 o'clock	4
	15.90	GP	General Condition photograph	0

+002.4m




2.4 m // 00:00:00

+009.3m




9.4 m // 00:00:00

+015.7m



15.9 m // 00:00:00

+028.8m



28.8 m // 00:00:00



## Inspection report

Date: <b>05/06/2009</b>	Job nr.: <b>T 6323</b>	Weather: <b>No rain or snow</b>	Operator: <b>Dan</b>	section number: <b>1</b>	PLR: <b>FW01 X</b>
Present:	Vehicle:	Camera:	Preset:	Cleaned: <b>No</b>	Grade:

1:124	position	code	observation	grade
	17.30	WL	Water level 5 % height/diameter	0
	18.20	WL	Water level 10 % height/diameter	0
	18.80	JN	Junction at 09 o'clock dia 100 mm	0
	19.20	DEC	Settled deposits hard or compacted 10 % cross-sectional area loss	
	19.30	WL	Water level 5 % height/diameter	0
	25.00	JN	Junction at 09 o'clock dia 100 mm	0
	27.40	CN	Connection at 12 o'clock, dia 100 mm	0
	28.10	LL	Line of drain/sewer deviates left	
	28.80	JN	Junction at 03 o'clock dia 100 mm	0
	28.80	H	Hole in sewer from 11 to 01 o'clock	4
	28.80	GP	General Condition photograph	0
	28.80	SA	Survey abandoned Camera stuck at Bend	0